



## FINAL UNIT (X45-391x-xx, X45-398x-xx) Schematic diagram



\*In the service manual, 2 x 470Ω (RK73FB2B471J) resistors are listed at the location of R24, R35 instead of the actually mounted C78, C79 (47pF). Please replace these capacitors with 1kΩ resistors.

## FINAL UNIT (X45-391x-xx, X45-398x-xx) Schematic diagram



## TX-RX UNIT (X57-785x-xx, X57-861x-xx) Schematic diagram

